



Detroit, MI
18239 S. Telegraph Road
Romulus, MI 48174
734-285-4860

Toledo, OH
3235 Molina-Martin Road
Millbury, OH 43447
419-836-4070

Sterling Heights, MI
5600 15 Mile Road
Sterling Heights, MI 48312
586-744-4815

*** Customer Review ***
Date / Time: 12/20/2019 8:13:55AM
Repair Order: 1564
Branch: Romulus
Invoice Total:
Charge
Page 1 of 3

Bill To:

Ship To:

X: (0) 0 -0

Customer P/O:

ehinds

Completion Date:

Unit Number: 31202

Model Year: 1900

Make/Model: Trail King Trailer

Type: Trailer

VIN: XM058329

Task: 1 01
Complaint:

General Trailer Repair

Department: Service

REMOVE WOOD FLOOR
REPLACE 18 CROSS MEMBERS
REPLACE FLOOR ON LOWER DECK
REPLACE 4 HANGERS
PLATE AND WELD NUMEROUS HOLES
BLAST AND PAINT FRAME BLACK
CHECK REAR LIFT AXLE
CHECK BRAKE - LEFT REAR SHOE OUTSIDE DRUM
CHECK S-CAMS
CHECK AIR TANKS AND VALVES
RE FASTEN ALL AIR LINES
CHECK FRONT VALVE AND CHAMBER N TONGUE WHERE PIN SLIDES
REPAIR FRONT PLATE AT 7-WAY AND HYDRAULIC LINES (FABRICATE A REMOVABLE PLATE)
REPLACE ALL BUSHINGS
REPLACE CAM BUSHINGS
REPLACE AIR TANKS
REPLACE BEARINGS
REPLACE BRAKES
INSTALL NEW DECALS
REPLUMB AIR SYSTEM
REPLACE ALL LIGHTS WITH LED
INSTALL NEW REF. TAPE

Supp. Part	Description / Ref Number	U/M	Quantity	Price	Ext
Shop Supp	Shop Supplies	Misc	1.00	60.00	60.00
eatccha	hose kits	Part	2.00		
S-22826-1	hanger	Part	EA 2.00		
S-22826-2	hanger 7.5" t	Part	EA 2.00		
S-20124	AIR BAG 9265	Part	EA 4.00		
S-20127	AIR BAG	Part	EA 2.00		
S-20002	SHOCK 230-250U	Part	EA 2.00		
S-13136	bushng kit y beam	Part	EA 4.00		
S3650/4	U-BOLT W/NUTS & WASHERS	Part	EA 4.00		
S-23651	SHOCK	Part	EA 2.00		
513020	RATCHET STRAP ASSY.2"X30'	Part	EA 1.00		
s-20131-1	r/s Y beam	Part	EA 1.00		
s-20131-2	C/S Y BEAM	Part	EA 3.00		
14X2 FSTL	STEEL 1/4"X2"	Part	EA 3.00		
43-7118	S-CAM KIT 1-5/8"	Part	EA 1.00		
10 lbeam	10lbeam	Part	EA 2.00		
12 l beam	12 l beam	Part	EA 2.00		



Be First Name In Trailers
www.lakeshoreutility.com

Detroit, MI
18239 S. Telegraph Road
Romulus, MI 48174
734-285-4860

Toledo, OH
3235 Moline-Martin Road
Millbury, OH 43447
419-836-4070

Sterling Heights, MI
5600 15 Mile Road
Sterling Heights, MI 48312
586-744-4815

*** Customer Review ***

Date / Time: 12/20/2019 8:13:55AM
Repair Order: 1564

Branch: Romulus
Invoice Total:

Charge

Page 2 of 3

Bill To:

Ship To:

Fax: (0) 0 -0

Customer P/O:	ehinds			Completion Date:
14x6 flat	14x6 flat	Part	EA	1.00
3/8x3x3 tube	tube	Part	EA	1.00
6 ibeam	6" ibeam	Part	EA	1.00
8 ibeam	8 ibeam	Part	EA	1.00
12 beam	junior beam	Part	EA	1.00
S-20924	ALIGN.WASHER INNER	Part	EA	4.00
S-20925	ALIGN.WASHER OUTER	Part	EA	4.00
4707	CORE BRAKE SHOE	Inherent		6.00
HV884707QG	Q+ BRAKE SHOE KIT 16-1/2"X7"	Part	EA	6.00
4707	23000			
TIM-413	CORE BRAKE SHOE	Part	EA	(2.00)
	BEARING/RACE SET	Part	EA	6.00
TIM-414	212011&212049			
	BEARING/RACE SET	Part	EA	6.00
CI05089	218210&218248			
372-7097	BRAKE CLEANER 19OZ	Part	EA	2.00
R955335	WHEEL SEAL GR/GD	Part	EA	6.00
447-4743	ABS SENSOR 1-FT**	Part	EA	2.00
	PRO-TORQ NUT TRAILER	Part	EA	6.00
300-4009	HM218248			
F5/16X3/4B	HUB CAP	Part	EA	6.00
F5/16LW	USS BOLT	Part	EA	36.00
S-30594-21L	LOCK WASHER	Part	EA	36.00
S-30594-21R	cam left	Part	EA	1.00
4707	cam right	Part	EA	1.00
461003	CORE BRAKE SHOE	Part	EA	(2.00)
1/4DC	AIR TANK 9.5"DIA. 27.5"H/C	Part	EA	2.00
3/8P	2-OPS PT			
AB1/2X3/8CE	DRAINCOCK	Part	EA	2.00
AB1/2X3/8CE45	PIPE PLUG	Part	EA	3.00
3/4X1/2B	ELBOW	Part	EA	1.00
1/2X1/4B	ELBOW 45	Part	EA	1.00
AB1/2X1/4CE	BUSHING	Part	EA	1.00
AB3/8X1/4CE	BUSHING	Part	EA	1.00
3/4P	ELBOW	Part	EA	1.00
AB3/8X1/4BT	ELBOW	Part	EA	1.00
S-24024	PIPE PLUG	Part	EA	1.00
90033785	BRANCH TEE	Part	EA	1.00
S-22619/2	SHOCK BOLT KIT	Part	EA	2.00
RBBTS-3030	MOUNT PLATE TOP AIRSPRING	Part	EA	1.00
AS1140	AIR SPRING MGT.KIT	Part	EA	6.00
F1/2X1-1/2B	BRAKE CHAMBER 3030			
F1/2LW	STD.13"PUSH ROD			
	AUTO SLACK 5.5 28T 1.5	Part	EA	4.00
	BOLT 1/2X1-1/2	Part	EA	20.00
	LOCK WASHER 1/2"	Part	EA	20.00
	FLAT WASHER 1/2"	Part	EA	20.00



First Name in Trailers
www.lakeshorautility.com

Detroit, MI
18239 S. Telegraph Road
Romulus, MI 48174
734-285-4860

Toledo, OH
3235 Moline-Martin Road
Millbury, OH 43447
419-836-4070

Sterling Heights, MI
6600 15 Mile Road
Sterling Heights, MI 48312
586-744-4815

*** Customer Review ***

Date / Time: 12/20/2019 8:13:55AM
Repair Order: 1564

Branch: Romulus
Invoice Total:

Charge

Page 3 of 3

Bill To:

Ship To:

Fax: (0) 0 -0

Customer P/O:		ehinds		Completion Date:	
F3/4NSAE	NUT SAE 3/4"	Part	EA	2.00	
F3/4LW	LOCK WASHER 3/4"	Part	EA	14.00	
B8736	CAM SUPPORT BRKT.	Part	EA	2.00	
4707	CORE BRAKE SHOE	Part	EA	(2.00)	
3922X	BRAKE DRUM	Part	EA	6.00	
AS1141	AUTO SLACK GUNITE 6"	Part	EA	2.00	
F3/4X3-1/2BGR8SAE	BOLT 3/4"X3.5"GD8	Part	EA	8.00	
F3/4NSAE	NUT SAE 3/4"	Part	EA	12.00	
F5/8X2-1/2BGR8	BOLT GRADE 8	Part	EA	2.00	
F5/8FW	5/8 FLAT WASHER GR8	Part	EA	4.00	
F5/8LW	5/8"LOCK WASHER	Part	EA	2.00	
HUBOIL	HUBOIL	Part	LBS	6.00	

Parts Quote:

Totals

Total Parts: _____
Total Core Chg: _____
Total Core Ret: _____
Total EHC: _____
Total Labor: _____
Total Miscellaneous: _____
Invoice Subtotal: _____
Total Tax: _____ \$0.00
Invoiced Total: _____

Payment Method

Charge

Authorized _____

Date _____

All charge invoices are due and payable by the net 30 days from date of invoice. past due accounts are subject to a delinquency charge of 1-1/2% per month which is an Annual Percentage Rate of 18%.